

Annexure D

BUILDING SAFETY CERTIFICATE

No.

Dated:

It is certified that the existing building A.U.A.N.Jha Govt. J. COLLEGE (name of the building or premises) at RAMPUR, ROAD, RUDRAPUR U.S. NAGAR (address) is having block(s)/Floor(s) as per details below:

Detail of Block(s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	Two	—	—	—	—	—

The building is owned/occupied by P.M. SHRI A.U.A.N.Jha G.I.C. Rudrapur (name of the Institution) have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of (Name of Department/ Govt.) on (date of inspection) in the presence of (name and addresses of the Manager/Secretary or his representative) and that the building/premises is fit for occupancy for running school with effect from for a period of years in accordance with rule and subject to compliance of the specific conditions as appended.

- 1.
- 2.
- 3.
- 4.

Issued on at by

* Strike out whichever is not applicable. In case of block is more than six use separate sheet for detail.

Signature with Seal : [Signature]
 Name : अशोक अमियन्ता
 Designation : समग्र शिक्षा
 Name & Address of Department/ Office : उधम सिंह नगर